

Roof Problem Details Report

Site: Campfire USA

Problem Status: OPEN 😞

Location:

Equipment: Old Building - North End



Relative Moisture: Barcode:

Asset ID: Condition: Inter-ply Moisture

IDN File: 53ed51f1-1864-4db2-b7f7-c9dfd6da7e74.idn

Severity:

Inspection#: 1	Image#: 1
Prob Date&Time: 04/21/2008 10:50	
Area Length: 3.5	
Area Width: 8	
Total Area: 28	



Component: Northwest Side - North side of Old building


Note: Possible Patch.

Probable Cause: Location showed possible moisture penetration.

Recommendation: Confirm with moisture probe and/or core sample.

Historical Sub Report

Insp.#	Prob.#	Date	Length	Width	Affected Area	Severity Code
1	1	04/21/2008	3.5	8	28	



Problem Status:	<input type="checkbox"/> Not repaired	<input type="checkbox"/> Repair made, but needs IR recheck	<input type="checkbox"/> Closed
Repair assigned to:	Repair target date:		
Repair assigned by:	Date:		
Repaired by:	Date:		
Type of defect found:			
Corrective action taken:			